GXS-700 X-ray Sensor Part 2



John McMaster JohnDMcMaster@gmail.com

Existing work

- Gave mtvre talk 3 years ago
- Made FOSS Gendex GXS-700 size 1 tools
- Same hardware in Dexis Platinum (right)





But wait! There's more

- Small size sensor for children ("size 2")
- Not supported since I didn't have a sensor




And then

- Customer wants size 2 support for project
- I say no since they want exclusive rights
- Eventually they agree to just support FOSS tool

A walk in the park?

- Should be easy project
- Already support closely related part
- Related capture, x-ray, etc infrastructure setup
- What could go wrong?


Project timeline



Getting samples

- Vendor reference image program not working
- Gendex / Dexis hack...possibly broke it?
- Sensor broken? They assured me no
- So had them capture samples, but...

Welcome to Windows



- Windows .pcap different than Linux .pcap
- Not as detailed
- Had to extend usbrply tool to support Windows

```
▼ USB URB

[Source: 3.2.0]

[Destination: host]

USBPcap pseudoheader length: 28

IRP ID: 0xfffffa8011069c60

IRP USBD_STATUS: USBD_STATUS_SUCCESS (0x00000000)

URB Function: URB_FUNCTION_CONTROL_TRANSFER (0x0008)

NRP information: 0x01, Direction: PD0 -> FD0

URB bus id: 3

Device address: 2

> Endpoint: 0x80, Direction: IN

URB transfer type: URB_CONTROL (0x02)
```

Still not working...

- Merged in changes from pcap, still doesn't work
- Eventually realized large sensor uses USB bulk transfers, but small uses interrupt transfers!
- How did I miss this?
 - I wasn't expecting this
 - Replay tool was set to omit these requests
 - Linux error messages were very generic

USB Interrupt Transfers

- Intended to be used for small ocassional events
- Primarily HID for keyboard / mouse
- Requires host to poll device
- Not inteded for large infrequent image transfers
- Why? Possibly small sensor doesn't have proper image buffer?

Things get worse

- I'm not familiar with USB Interrupt transfers
- Relatively poorly documented since rarely used
- Wasn't exactly sure how to use the interface, but fiddled with it until it worked
- Then customer tried to use the code and...


```
def interruptRead(self, endpoint, length, timeout=0):
    """
    Synchronous interrupt write.
```


A slew of problems

		themal nonite and supplicit Blift Banden menerit sould be fill weither
ļ		Kernel panic - not syncing: DMA: Random memory could be DMA written
]	107.290294]	
]		CPU: 0 PID: 3340 Comm: python Tainted: P DX 3.13.0-68-generic #111-Ubuntu
Ĩ		Hardware name: LENOVO 4282AH4/4282AH4, BIOS 88ET62WW (1.42) 07/26/2013
]	107.290570]	000000000314200 ffff8800ac44bb98 fffffff817240e0 ffffffff81a91820
]	107.290658]	ffff8800ac44bc10 fffffff8171cf63 000000000000008 ffff8800ac44bc20
]	107.290742]	ffff8800ac44bbc0 fffffff8171da8e 000000000000046 000000000000000
]		
]	107.290867]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
]	107.290926]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
]	107.290981]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
]	107.291039]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
	107.291106]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
]	107.291176]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
Ι	107.291244]	<pre>[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<></pre>
]	107.291314]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
I	107.291378]	<pre>[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<></pre>
Ι	107.291444]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
I	107.291509]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
]	107.291569]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
Ī	107.291634]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
Ī	107.291697]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
Ī	107.291755]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
Ī	107.291817]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
i	107.291875]	[<ffffffffffffffffffffffffffffffffffff< td=""></ffffffffffffffffffffffffffffffffffff<>
Ī	107.291951]	drm_kms_helper: panic occurred, switching back to text console
-	TALICATION]	

The world is on fire!

- Some native Linux: kernel panic
- VirtualBox: crashes Windows host
- Some systems yield corrupt image





What happened?

- Improper Interrupt transfer works on some systems
- Relatively recent kernels still had insufficient error checking
- Must keep alignment, even though over-reads device

```
self.dev.setInterfaceAltSetting(0, 1)
all_dat = bytearray()
while len(all_dat) < self.FRAME_SZ:
        all_dat += self.dev.interruptRead(2, self.FRAME_SZ, t
        all_dat += self.dev.interruptRead(2, 1024, timeout=50
# Packet 12961
self.dev.setInterfaceAltSetting(0, 0)</pre>
```

Takeaways

- Bill by hour, not by project => \$win
- Customer was happy despite under estimate due to clear communication
- Hard to estimate some projects up front
- Learned a little about Windows kernel USB
- Learned more about USB

Thanks!

- Questions? Interested?
 - JohnDMcMaster@gmail.com
- http://siliconpr0n.org/media/mtvre/2015-04-08_john_m_x-ray.pdf
- https://github.com/JohnDMcMaster/uvscada
- https://siliconpr0n.org/nuc/doku.php? id=gendex:gxs700